Process Safety Forum

The Process Safety Forum consists of representatives from UKPIA, TSA, CIA, OGUK and NIA

Process Safety Alert 006

Issued on:

Issued by:

1st June 2011

Process Safety Forum

Subject:

Floating Roof Tank Rainwater Drains Integrity Issues

Issue

An incident involving external floating roof tanks highlight the risks associated with open and closed roof drain valves.

Incident

A gas detector alerted operations to a possible hydrocarbon leak near the tankfarm area. Shift personnel immediately investigated the area and found gasoline/condensate



escaping from the roof drain outlet at one of the double deck floating roof tanks. The gas cloud that formed had triggered a nearby gas detector. The release led to excess emissions and a difficult cleanup but no injuries.

How did this happen (Causes of incident)

The release of gasoline came from a six inch floating roof drain system that is provided to remove rainwater from the tank roof to the tank bund. The system has a series of arms moving at the swivel joints as the roof moves up and down (see figure 2).

The connection between the drain system and the floating roof failed. The failure of the drain system led to material flowing through the normally open drain valve into the dike area.

