

## Dubai Fabrication Facility

---


# Pipe Stacking Fatality



August 10, 2001


# Stage A

Original Configuration




## Stage B

Tubular no. 1 was repositioned to the end of the stack




## Stage C

Tubular no. 2 was repositioned to expose tubular no. 3




# Stage D

Tubular no. 3 was removed from the bottom tier and placed clear of the stack




## Stage E

Rigger #1 enters the space created by the removal of tubular no. 3. The reason for his action is uncertain - but believed to be to position a stabilising chock, or to follow a tag line which was attached to tubular no. 3.



# Stage F

The two tier stack collapsed and crushed Rigger #1 between tubulars no. 4 and no. 5.



## Incident Scene

