



Transformer ruptured  
upper left seam of shell



Unit 2 Unit Transformer



Unit 2 Generating Transformer  
no suspected damage.

